City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| IX. Notification to the Public | | | | |
| A. Accessibility of Parks and Rec Facilities and Programs: | 1/30/2004 | | | |
| 1. Provide accessibility information on all Parks published material | | Completed | | Ramp to playground at Snyder Park does not provide edge protection. |
| 2. Provide accessibility information on Parks website | | Completed | | http://ci.ftlaud.fl.us/cityparks/ada.htm |
| 3. Provide public information materials in different ADA compatible formats | | Completed | | |
| 4. Maintenance program for accessible features | | | | |
| | | | | |
| B. Event Notification: | 10/31/2003 | | | |
| 1. Notification of accommodations | | Completed | | |
| | | | | |
| C. Event Seating Notification: | 10/31/2003 | | | |
| 1. Notification of disabled seating | | Completed | | |
| 2. Advanced ticket and seating system (telephone number) for the disabled | | | | |
| | | | | |
| D. Alternative Formats of City Materials: | 10/31/2003 | | | |
| 1. Published materials state alternative formats for vision impaired are available | | Completed | | |
| | | | | |
| E. Employment Notices: | 10/31/2003 | | | |
| 1.Published materials and website state to contact a designated City representative for reasonable accommodation during job application process. | | Completed | | http://www.ci.ftlaud.fl.us/jobs/employment_info.htm |
| | | | | |
| X. ADA Grievance Procedures: | 1/30/2004 | | | |
| 1. Publish procedures for prompt and equitable resolution of complaints | | Not done | | |
| 2. Designate an office to investigate and respond to complaints | | Not done | | |
| 3. City's website to post it's grievance procedures and method to send complaints via the internet | | Not done | | |
| | | | | |
| XI. Designation of ADA Coordinator: | 10/31/2003 | | | |
| 1. Designate a properly trained staff person as "ADA Coordinator" | | | | |
| 2. City shall publish name, office address and telephone number of coordinator | | Not done | | |
| 3. Designate "Event Coordinators" to address the needs of the disabled | | Not done | | |
| 4. Provide information on the City's on the duties of the ADA Coordinator and Event Coordinators and types of assistance provided to the public | | Not done | | |
| 5. Designated ADA Coordinator to have a published TTY telephone number | | Not done | | Bellsouth white pages does not provide a listing for the ADA coordinator. |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| XII. Maintenance of Accessible Features: | 10/31/2003 | | | |
| 1. Provide a system for maintenance and repair of accessible equipment | | Incomplete | | |
| | | | | |
| XIII. Communications: | | | | |
| A. TTY Telephone Service | | | | |
| 1. All TTY numbers for City offices published in all City phone directories | 1/30/2004 | | | |
| | | | | |
| B. Sign Language Interpretation: | 10/31/2003 | | | |
| 1. Procedures for prompt procurement of quailified interpreting services upon request | | Not done | | An interpreting service has not been procured. |
| | | | | |
| C. Auxiliary Aids & Services: | 10/31/2003 | | | |
| 1. Provide appropriate auxiliary aids and services when necessary | | | | |
| | | | | |
| D. Fixed Assistive Listening System in Public Meeting Room: | 1/30/2005 | | | |
| 1. Provide at least 1 meeting room with permanent installed assistive listening system | | | | |
| | | | | |
| E. Signage and Notice: | 10/31/2003 | | | |
| 1. In each City facility where axiliary communications are regularly provided, City shall post appropriate signage indicating where such materials are provided. | | | | |
| | | | | |
| F. Closed Captioning Television Decoders: | 7/31/2004 | | | |
| 1. All Tvs used in public events to be equipped with closed caption decoders | | | | |
| | | | | |
| G. Portable Assistive Listening Equipment: | 1/30/2004 | | | |
| 1. At least 4 portable assistive listening devices are readily available upon request | | | | |
| | | | | |
| H. Closed Captioning of Televised City Commission Meetings: | | | | |
| 1. A committee formed to investigate the feasibility of closed captioning of City Commission meetings | 7/31/2004 | | | |
| 2. Committee to prepare a report outlining costs to provide such closed captioning | 7/31/2005 | | | |
| | | | | |
| I. Advanced Ticketing and Seating for City Programs and Activities: | 10/31/2003 | | | |
| 1. City shall ensure that appropriate number of wheelchair and companion seating are held available. | | | | |
| | | | | |
| XIV. City Website Accessibility and Usability: | 7/31/2004 | | | |
| 1. Images on website to include "alt tags" long descriptions and captions as needed | | Completed | | www.ci.ftlaud.fl.us/accessibility.htm |
| 2. All online forms and tables to comply with assessible website design guidelines | | Completed | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 3. All documents posted on website to be available in HTML or test-based format | | Completed | | |
| | | | | |
| XV. Accessibility of City Sidewalks & Intersections: | 10/31/2003 | | | |
| A. Public Comment | | | | |
| 1. City shall post notices in City newsletters and website that invite interested | | | | |
| persons to identify and request necessary improvements to public sidewalks. | | | | |
| 2. Notices to include name, office location and phone # of staff to receive comments | | | | |
| 3. Notices shall be provided for a minimum of 24 mos. from the date of agreement | | | | |
| | | | | |
| XVI. Accessibility of City Parking Lots & Parking Structures | | | | |
| A. Self -Evaluation of Public Parking Facilities | 7/30/2005 | | | |
| 1. City shall perform and complete a self-evaluation of all City owned and controlled | | | | |
| public parking facilities to identify locations that lack the requisite number of | | | | |
| of disabled parking spaces. | | | | |
| | | | | |
| XVII. City "One Stop Shop" Facility: | | | | Relocated to 700 N.W. 19 Ave. |
| A. Disabled Parking Spaces | 10/31/2003 | | | |
| 1. Existing disabled parking spaces to fully comply with dimensional, signage and | | | | |
| location requirements and ensure parking spaces connect to accessible route | | | | |
| | | | | |
| B. Accessible Route from Disabled Parking Spaces to Facility Entrance | 10/31/2003 | | | |
| 1. Provide accessible route from disabled parking to West facility entrance | | | | |
| 2. Route to be designated by permanent ground markings and directional signage | | | | |
| 3. Install proper handrails on stairs to facility entrance | | | | |
| | | | | |
| C. Public Restrooms | 10/31/2003 | | | |
| 1. Interim measures until relocation include installing proper toilet stall grab bars, | | | | |
| sink wraps and lowering dispensers to proper reach ranges. | | | | |
| | | | | |
| XIX. City Police Station, 1300 Broward Blvd. | | | | |
| A. Curb cuts & Accessible Exterior Path of Travel | 10/31/2003 | | | |
| 1. All disabled park. spaces connect with accessible path to accessible entrances | | Incomplete | 6,7 | Disabled parking spaces do not connect to an a accessible path as proper curb ramps are not provided. |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 2. Proper curb cuts are provided along accessible path to any elevated area on route | | Incomplete | 4,5 | Curb ramp from sdewalk to facility provides a 1.25" change of level at bottom at ramp. Curb ramp on west side from accessible parking spaces does not provide a level landing at top of ramp. Curp ramp on east side from accessible parking spaces provides flared sides with execessive slopes. |
| | | | | |
| B. Public Telephone | 7/31/2004 | | | |
| 1. All public phone banks provide hearing impaired features and necessary height and clear floor space for wheelchair users | | Incomplete | 8,9 | Volume controls are not provided on the public phone or the public records phone. |
| | | | | |
| C. Public Restrooms | 7/31/2004 | | | |
| 1. Provide proper signage to identify location of accessible restrooms | | Complete | | |
| 2. Provide wheelchair accessible toilet stalls, sinks and all dispensers and amenities located with proper reach ranges | | Incomplete | 10,11,12, 13,14 | Compliant maneuvering door clearance is not provided on exit side of the door. Compliant maneuvering clearances are not provided at the accessible stall door. A compliant rear grab bar is not provided in the toilet stall. Lavoratory does not provide compliant wrap. Lip of urinal is mounted at a non-compliant height. |
| 3. If City can't make alterations to provide proper turning radius, a unisex accessible restroom shall be constructed | | Not Done | | A unisex accessible restroom is not provided. |
| | | | | |
| D. Wheelchair Accessible Prisoner Holding Cell | 7/31/2004 | | | No access at time of inspection |
| 1. Provide an accessible toilet and sink facilities | | | | |
| 2. Provide the requesite interior dimensions for a wheelchair turning radius | | | | |
| | | | | |
| E. Wheelchair Accessible Prisoner Exercise Area. | 8/30/2003 | | | No access at time of inspection |
| 1. Provide an exercise location with equivalent facilitation for disabled persons | | | | |
| | | | | |
| XX. Swimming Hall of Fame Aquatic Complex | | | | |
| A. Accessible Path of Travel from City Sidewalk | 1/30/2004 | | | |
| 1. Provide an accessible route from sidewalk to all facilities within the complex | | Incomplete | 4,5 | The door threshold at the gift shop is 1.5" high. |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 95[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 2. Accessible route does not rquire travel through a roadway or behind parked cars | | Complete | 1,2,3 | |
| 3. Post appropriate directional signage to location of all accessible routes in complex | | Complete | | |
| | | | | |
| B. Disabled Parking | 7/30/2004 | | | |
| 1. Provide proper number of disabled parking spaces and are properly dispersed to | | Complete | | |
| evenly provide access to the multiple entrances of the complex. | | | | |
| 2. All disabled parking spaces directly connect on accessible route and do not | | Complete | | |
| require travel through a roadway or behind parked vehicles. If infeasible or would | | | | |
| require loss of more than 5% of available spaces, then permanent ground | | | | |
| markings of safest accessible route through the roadway shall be provided. | | | | |
| | | | | |
| C. Parking Lot Entry/Exit System | | | | |
| 1. City shall discontiue use of existing token operated entry/exit system | 7/30/2005 | Complete | | |
| 2. Future system for parking fees and entry/exit to parking to provide full accessibility | | Complete | | |
| 3. In the interim, City shall post informational signage in area of all disabled parking | 10/30/2003 | Complete | | |
| spaces and at all accessible entry/exit points of facility indicating the procedure | | | | |
| and locations for assistance. | | | | |
| | | | | |
| D. Museum/ Display Area Public Restrooms (2nd Floor) | 3/30/2004 | | | |
| 1. Make alterations to door thresholds, open force of entry doors | | Incomplete | 6, | Accessible entrance of museum door entry does not provide a level landing. |
| 2. Provide compliant maneuvering space at all entry doors | | Incomplete | 13,14,15, 16 | The Bob Alexander room entrance provides only a 30" width clearance. The accessible path in the Bob Alexander room is only 40" in width and does not provide compliant wheelchair turning space. The Henning library provides a door threshold of 1" high and the library does not provide an accessible route to first or second floor amenities. |
| 3. Relocate dispensers and amenities within compliant reach ranges. | | Incomplete | 10, 12 | Museum second floor women's restroom provides a coat hook mounted at a non-compliant height. Also men's restroom stall provides a coat hook mounted at a non- compliant height. |
| 4. Policy change to allow access to restrooms w/o payment of museum fees | | Complete | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 5. Post appropriate signage on 1st floor indicating the location of accessible restroom on second floor | | Incomplete | 7 | Museum first floor directional signage at non-accessible restrooms to accessible restrooms is not provided. |
| 6. Provide accessible stalls, urinals, and compliant clear floor space | 7/30/2006 | Incomplete | 10,11,12 | Museum second floor men's restroom door provides an excessive pressure to open. Museum second floor women's restroom toilet provides a flush valve not mounted on the wide side of the toilet |
| | | | | |
| F. Training, Competition, and Stadium Facilities: | | | | |
| iii) Ticket Booth Counter | 7/30/2005 | | | |
| 1. Provide an accessible counter | | Incomplete | 22 | Counter is mounted at a non-compliant height. |
| | | | | |
| v.) Locker Room Facilities | 10/30/2003 | | | |
| 1. Provide proper grab bars at accessible toilets | | Incomplete | 18,19,20, 21 | Locker room facilities does not provide compliant grab bars. |
| | | | | |
| G. Hall of Fame Facility (West End of Complex) Swimming | 10/30/2003 | | | |
| 1. Proper handrails along Access ramp and entrance steps | | Complete | | |
| 2. Proper directional signage to accessible entrances | | Complete | | |
| 3. Repair of wheelchair accessible entry system | | Complete | | |
| | | | | |
| ii.) Public Restrooms (2nd Floor) | 10/30/2003 | | | |
| 1. Provide directional signage to accessible route to 2nd floor restrooms | | Complete | | Gift shop first floor does provide directional signage to accessible restrooms on second floor. |
| 2. Post directional signage at all inaccessible restrooms and elevator locations | | Complete | | |
| 3. Install proper toilet stall grab bars | | Incomplete | 24,25,26, 27,28,30, 31 | Gift shop men's and women's restroom accessible stalls do not provide compliant grab bars. Also coat hooks are mounted at non-compliant heights. |
| 4. Ensure accessiblility of restroom entrances and door hardware | | Incomplete | 23,29 | Gift shop men's and women's restroom accessible stalls do not provide compliant maneuvering clearance at the doors. |
| | | | | |
| iii.) Water Fountain Access | 10/30/2003 | | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954 -0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 1. Install a cup dispenser adjacent to fountain on the first floor | | Incomplete | 9 | Cup dispenser does not provide cups. |
| | | | | |
| XXI. War Memorial Auditorium | | | | |
| B. Disabled Parking & Accessible Path of Travel to Auditorium | | | | |
| i.) Additional Disabled Parking Spaces: | 7/30/2005 | | | |
| 1. Provide at least 10 accessible parking spaces | | Incomplete | 1,2,3,4,5,6,7,8 | The 10 accessible spaces do not provide compliant access aisles. Also the accessible parking spaces are not level as there is vegetation overgrowing the spaces. The accessible space markings are faded and in poor condition. |
| 2. Disabled parking spaces to connect to accessibe route that does not require travel in roadways or behind parked vehicles. | | Incomplete | 9,10,11,12 | Accessible parking spaces do not connect to an accessibe route that does not require travel in roadways or behind parked vehicles |
| | | | | |
| ii.) Wheelchair Accessible Paths of Travel | 7/30/2005 | | | |
| 1. Provide an accessible route from disabled spaces to entrances | | Incomplete | 13,14,15, 16,17,18 | An abrupt change of level of greater than 1" high is present along the accessible route and at the bottom of the ramp to the faciities. |
| 2. Where the accessible route must cross any roadway, permanent ground markings to indicate a safe area for crossing and ensure that proper curb cuts are provided to serve any elevation along the route | | Not Done | 12 | Permanent ground markings to indicate a safe area for crossing are not provided where the accessible route must cross the roadway. |
| | | | | |
| iii.) Alteration of Existing Disabled Parking Spaces | 7/30/2004 | | | |
| 1. Make necessary alterations of existing disabled parking spaces to provide proper widths and signage | | Incomplete | 1,2,3,4,5,6,7,8 | The existing disabled parking spaces do not provide compliant access aisles. |
| | | | | |
| iv.) Exterior Paths of Travel to Facility | 7/30/2005 | | | |
| 1. Provide accessible route including sidewalks, curb ramps and transition areas | | Incomplete | 13,14,15, 16,17,18 | An abrupt change of level of greater than 1" high is present along the accessible route and at the bottom of the ramp to the faciities. |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 2. Post directional signage to accessible routes at all in accessible pathways | | Incomplete | | Directional signage to accessible routes at all inaccessible pathways is not provided. |
| | | | | |
| C. Exterior Access Ramp to Auditorium Entrance | 7/30/2005 | | | |
| 1. Provide proper handrails along the full length of the existing access ramp | | Incomplete | | Compliant handrail extensions are not provided at the top of the accessible ramp to the facility. |
| 2. Provide smooth transition at base of ramp | | Complete | | |
| | | | | |
| D. Exterior Steps to Facility Entrance | 7/30/2005 | | | |
| 1. Provide at least 2 handrails with proper extensions to serve the entrance steps | | Complete | 20,21,22 | |
| | | | | |
| E. Lobby Ticket Counter | 7/30/2005 | | | |
| 1. Provide compliant counter heights, maneuvering space and knee clearance. | | Not done | 23 | Compliant counter heights, maneuvering space and knee clearance are not provided. |
| 2. Provide at non-compliant counters, directional signage to accessible counters | | Not done | 23 | Directional signage at non-compliant counters to accessible counters is not provided. |
| | | | | |
| F. Signage Indicating Location of Auxilliary Communication Aids | 7/30/2005 | | | |
| 1. Provide signage at all ticketing areas to indicate location for requesting auxilliary communicating aids | | Complete | 26 | |
| 2. At location where aids are provided, post any policy for the receipt and/or use | | Complete | 26 | |
| | | | | |
| G. Access Ramp from Lobby to Auditorium Level | 7/30/2005 | | | |
| 1. Provide proper handrails along the access ramp and ensure that the landing area remain free and clear of any obstacles (event seating, vendors' booths, etc.) | | Incomplete | 31,45 | Compliant handrails with extensions are not provided on access ramp from lobby to auditorium level. |
| | | | | |
| H. Public Restrooms | 7/30/2005 | | | |
| 1. Provide accessible men's and women's restrooms | | Incomplete | | Compliant accessible restroom signage is not posted at restroom entrances. |
| 2. At non-accessible restrooms provide directional signage to accessible restrooms | | Not done | 27 | Directional signage at non-accessible restrooms to accessible restrooms is not provided. |
| | | | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 95[illegible]6-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| I. Wheelchair Lift to Auditorium Stage Level | 10/30/2003 | | | |
| 1. Ensure wheelchair lift is in proper working condition for all events | | Not done | | Wheelchair lift was not installed at time of inspection. |
| 2. Post proper signage indicating location to request assistance with wheelchair lift | | Not done | | Compliant signage was not posted at time of inspection. |
| | | | | |
| J. Stage Level Wheelchair Access Ramp | 7/30/2005 | | | |
| 1. Provide an accessible path from auditorium level to the stage level and route to be located nearest to accessible seating area | | Incomplete | | A ramp or lift was not provided at time of the inspection. |
| | | | | |
| K. Auditorium Level Exit Doors | 7/30/2005 | | | |
| 1. Provide accessible entrance doors and emergency exits on the auditorium level wth proper upper and lower flat landing areas, ramp slopes and handrails | | Not done | 35,36,37, 39, 40, 41,42 | A non-compliant threshold of greater than 1" high is provided at the meeting room entrance. Emergency exits do not provide compliant accessible ramps or compliant level landings. Also the stairs at the emergency exits do not provide compliant handrails and handrail extensions. |
| | | | | |
| XXII. Holiday Park Social Center | | | | |
| A. Disabled Parking and Accessible Path of Travel to Entrance | 7/30/2005 | | | |
| 1. Relocate disabled parking spaces to the nearest accessible location to entrance | | Complete | | |
| 2. Provide compliant parking spaces at this location and accessible path does not require travel behind parked cars or travel in any roadway area | | Incomplete | 47 | Compliant signage is not posted at a disabled parking space. |
| | | | | |
| B. Public Restrooms | 1/30/2004 | | | |
| 1. Provide compliant accessible restrooms | | Incomplete | 52 | Men's restroom accessible toilet provides a flush valve that is not mounted on the wide side of the toilet area. |
| 2. Provide compliant restroom signage | | Complete | 48,49 | |
| 3. Provide clear line of sight from toilet stalls to visual emergency alarms | | Complete | | |
| 4. Provide compliant directional signage at non- accessible RR to accessible RR | | Complete | | |
| | | | | |
| XXV. Morton Center Facility & Floyd Hull Stadium | | | | |
| A. Notice to Facility Lessee | 10/30/2003 | | | |
| 1. Provide notice to lessee which outlines the barriers to disabled persons | | | | Not examined |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| | | | | |
| D. Signage Indicating Location of Accessible Children's Playground Facility | 1/30/2004 | | | |
| 1. Provide proper signage adjacent to parking area indicating location of nearest accessible playground facility | | Complete | 59,60 | Directional signage is mounted at a height which can be easily obstructed by a parked vehicle. |
| | | | | |
| F. Restroom Directional Signage | 1/30/2004 | | | |
| 1. Provide proper directional signage at baseball facilities to accessible restrooms | | Incomplete | 64 | Men's restroom does not provide directional signage to accessible restrooms |
| | | | | |
| XXVI. Snyder Park | | | | |
| I. Beach Facility | | | | |
| ii.) Access Route to Beach | 1/30/2005 | | | |
| 1. Provide alterations to provide smooth flat transitions at each end of sloped route | | Complete | 71 | |
| | | | | |
| iii.) Exterior Stair Handrails | 1/30/2005 | | | |
| 1. Provide proper handrails along stairs leading to beach area | | Not done | 72 | Compliant handrails are not provided along stairs leading to the beach area. |
| | | | | |
| XXVII. Fort Lauderdale Beach Facilities | | | | |
| A. Informational Signage Indicating Lcation of Accessible Features & Facilities | 7/30/2004 | | | |
| 1. Within beach's public areas, provide directional signage to accessible amenities such as accessible restrooms, showers, disabled parking, accessible access points to beach and location of beach chairs for disabled persons | | Incomplete | 20,21,22, 23,24 | Accessible shower at Sebastian street does not provide compliant headroom clearance and an accessible route is not provided to the playground. Directional signage to accessible amenities at all the beaches public areas is not provided. |
| | | | | |
| B. Informational Signage Posting City's Service Animal Policy | 10/30/2003 | | | |
| 1. Amend any posted policy re: to include service animals to disabled persons | | Incomplete | 52 | Signage posted at the south end of South Beach states that dogs and pets are not permitted on the beach |
| | | | | |
| E. South Beach Facilities: | | | | |
| ii.) Accessible Sidewalk & Directional Signage | 1/30/2004 | | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954 876-0209
Fax: 954 [illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 1. Provide directional signage at the North and South ends of South Beach Park where the sidewalk on the East side of A1A ends at each location and signage will indicate the nearest accessible route across A1A which provides curb cuts to the elevated sidewalk level | | Incomplete | 57 | Directional signage at the North and South ends of South Beach Park where the sidewalk on the East side of A1A ends at each location and signage that indicates the nearest accessible route across A1A which provides curb cuts to the elevated sidewalk level is not provided. |
| | | | | |
| iii.) Accessible Location for Public Transportation Stop | 10/30/2003 | | | |
| 1. Provide notice to Broward County Transit that the stop located adjacent to South Beach Park is inaccessible and shall request a relocation on accessible route from sidewalk to South Beach Park | | Not done | 25,26,27 | The Broward County Transit stop located adjacent to South Beach Park is inaccessible from sidewalk to South Beach Park |
| | | | | |
| iv.) Disabled Parking | 1/30/2004 | | | |
| 1. Provide accessible parking spaces, signage and connect to an accessible path to accessible restrooms, picnic areas and public walkways to beach areas | | Not done | 29,30,31, 32,33,34, 37,38,39, 40,41,42, 43,48,49, 50 | Accessible parking spaces are not properly disbursed as accessible parking is not provided at south end of South Beach facilities. An accessible path is not provided from the sidewalks to the facilities as the ramps provide excessive slopes and existing ramps do not provide compliant handrails. The accessible route provides areas with non-compliant cross slopes at curb ramps. Also the curb ramps provide flared sides with non-compliant slopes. |
| v.) Signage Indicating Location of Beach Chairs for Disabled Use | 1/30/2004 | | | |
| 1. Post signage at/near location of disabled parking indication location to request beach chair amenities for disabled persons | | Not done | 28,32, 37,43,48 | Signage at/near location of disabled parking is not provided indicating location to request beach chair amenities for disabled persons. |
| | | | | |
| vi.) Public Restrooms | 1/30/2004 | | | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 1. Ensure the accessible restrooms are maintained in proper working order and opened during all hours that South Beach parking remains open to public | | Not done | 44,45,46, 47 | Men's and Women's restrooms do not provide compliant grab bars. Also the toilet seat in the women's restroom is broken. Men's restroom lavoratory does not provide compliant pipe wrap. |
| 2. Provide an accessible shower adjacent to restroom facility | | Complete | | |
| | | | | |
| F. Las Olas Parking Lot | 1/30/2004 | | | |
| 1. Provide the proper number of disabled parking spaces with proper dimensions, and access aisles with proper signage | | Complete | | |
| 2. Disabled parking spaces to connect an accessible route to public sidewalks and do not require travel in roadways or behind parked vehicles | | Complete | | |
| | | | | |
| G. Intracoastal Parking Lot | 1/30/2004 | | | |
| 1. Provide the proper number of disabled parking spaces with proper dimensions, and access aisles with proper signage | | Complete | 10,11,12, 13,14,15, 16,17,18 | |
| 2. Disabled parking spaces to connect an accessible route to public sidewalks and do not require travel in roadways or behind parked vehicles | | Complete | 16 | |
| | | | | |
| H. Sebastian Street Disabled Parking Lot | 1/30/2004 | | | |
| 1. Provide the proper number of disabled parking spaces with proper dimensions, and access aisles with proper signage | | Complete | 1,2,3,4,5,6 | |
| 2. Disabled parking spaces to connect an accessible route to public sidewalks and do not require travel in roadways or behind parked vehicles | | Complete | 5,6 | |
| 3. Provide proper handrails along the access ramp serving the disabled parking area | | Not done | 7,8,9 | Compliant handrails along the access ramp serving the disabled parking area are not provided. |
| | | | | |
| XXVIII. Fort Lauderdale Baseball Stadium | | | | |
| A. Disabled Parking and Path of Travel to Ticketing Area: | 7/30/2005 | | | |
| 1. Provide at least 8 accessible parking spaces with adjacent access aisles | | Completed | | |
| 2. Accessible route shall be located so uses do not travel behind parked cars and | | Completed | | |
| and where route must cross a roadway, painted ground marking will indicate route | | | | |
| | | | | |
| E. Public Restrooms (South Side) | 1/30/2005 | | | |
| 1. Provide proper accessible restrooms, toilet stalls | | Completed | 1 | |
| 2. Provide compliant alternate ambulatory accessible stall where necessary | | Completed | 2 | |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210

City of Ft. Lauderdale
ADA Inspection Report

| Work to be Completed | Deadline | Progress | Photo | Notes |
|---|---|---|---|---|
| 3. Provide proper restroom signage | | Completed | | |
| | | | | |
| F. Wheelchair Seating and Wheelchair Companion Seating areas (West side) | 1/30/2005 | | | |
| 1. Provide proper painted ground markings indicating width and location of | | Completed | | |
| designated wheelchair seating locations | | | | |
| 2. Maintain a supply of wheelchair companion portable seating readily available | | Completed | | |
| | | | | |
| G. Access Ramps to Stadium Seating Level | 1/30/2005 | | | |
| 1. Provide proper handrails at both ramps | | Completed | | |
| 2. At base of each ramp, provide proper signage indicating route to accessible | | Completed | | |
| seating location. | | | | |
| | | | | |
| XXIX. Lockhart Stadium | | | | |
| A. Disabled Parking and Paths of Travel to Facility Entrance | 7/30/2004 | | | |
| 1. Provide the proper number of disabled parking spaces with proper dimensions, and access aisles, with proper signage | | Incomplete | 28 - 30 | Proper signage is not provided at 12 parrallel accessible parking spaces. |
| | | | | |
| D. Accessible Restrooms | 7/30/2004 | | | |
| 1. Provide accessible restrooms at location closest to wheelchair seating area | | Incomplete | 7,13,14,24 ,25,26,27 | N.E. Accessible restrooms do not provide a compliant "B" stall. Also the S.W. accessible restrooms do not provide compliant "B" stalls. In the S.W. accessible restrooms, there are toilet paper dispensers mounted over the side grab bar. |
| 2. Provide proper directional signage to accessible restrooms at all inaccessible restrooms and throughout the facility. | | Incomplete | 5-12,19, 21, 22 | Proper directional signage is not provided at all inaccessible restrooms. Also it should be noted that the accesible sign at the NW inaccessible restroom should be removed. |
| | | | | |
| XXXII. Parks & Recreation Department Facility, 1350 W. Broward Blvd. | | | | |
| B. Accessible Rear Entrances (Interim Solution) | 7/30/2004 | | | |
| 1. Provide proper signage at front entrance indicating accessible entrance in rear of | | Complete | | |
| facility | | | | |
| 2. Provide buzzer and proper signage indicating procedure for use | | Complete | 3 | |
| 3. Provide proper rear door hardware and accessible door entry | | Incomplete | 1,2 | The rear entrance door provides a threshold of one inch in height. |

ADA Compliance Team, Inc.
169 NW 44 St Suite #34
Ft. Lauderdale, Fl. 33309
Phone: 954-876-0209
Fax: 954-[illegible]-0210